


898533 0 0 851484






FIG. 2




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 3A




FIG. 3B

FIG.4A




FIG.4B





FIG.4C



00853770.051101




FIG.4D




FIG. 5




FIG. 6




FIG. 7





FIG. 8






FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18

09853770 051101




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28

AUTOMATIC TELLER MACHINE 401




FIG. 29

NETWORK 411




FIG. 30




FIG. 31




FIG.32A




FIG.32B




FIG.33




FIG. 34




FIG. 35

29353738




FIG. 36




FIG. 37





FIG. 38

**FIG.39**




FIG. 40




FIG.41




FIG.42




FIG.43




FIG. 44




FIG. 45




FIG.46




FIG.47
PRIOR ART




FIG.48
PRIOR ART